

TO Office of State Engineer  
Attn: Donald G. Norseeth  
State Capitol Building  
Salt Lake City, Utah

COMMISSIONER'S MONTHLY REPORT

Commissioner

BOARDMAN SPRING, THOMAS SPRING AND VICINITY

Date July 22 1965  
Report for Month of July 1965

Source and Point of Measurement

	Day of the Month														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
I. Boardman Springs															
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)															
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)															
#3. Church ditch near to heading															
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)															
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake															
II. Thomas Spring															
#5. Above the Olsen house below the tracks															
III. Drain															
#6. Drain Channel near Railroad Shop and Birmingham properties															
IV. #8. Levie Ditch - water to Church Farm, etc.															
V. #9. Pump Water at Church Welfare Farm															

For key to location numbers see drawing P-5107

Note all Boardman water was going to P.S. C.I.P.G. on both July 8 and July 22.

Submitted by

E. Lewis Allen

Note little pumping of Boardman & Thomas waters  
This is traditional & important.